

Name: _____
 Phone #: _____

Kiln: Electric #2
 Firing Type Cone 04 Ox
 Cones Top: _____
 Middle: 06/04/03
 Bottom: _____

BROGDEN/ KILN CHART SAMPLE

You must be present when firing the electric kilns to make sure they shut off ... Sometimes they do not!

DAY	TIME		Temp	Comments
DAY #1	3:00 PM		LOW LOW LOW	Small Cone 03 in sitter Cone Pack : 06/04/03 Top spie out Lower spies all in Timer to 20 hrs
	5:00 PM		LOW LOW MED	ALL SPIES IN
OVER NIGHT TO BUILD EVEN HEAT				
DAY #2	8:00 AM		MED MED HIGH	Timer To: 8 Hours Only Red Heat
	10:00 AM		HIGH HIGH HIGH	
	10:30 AM			Start checking kiln ever 20 minutes When sitter or cones fall, turn all switches to OFF