

Name: \_\_\_\_\_  
 Phone #: \_\_\_\_\_

Kiln: Electric #2  
 Firing Type Cone Six Ox  
 Cones Top: \_\_\_\_\_  
 Middle: 5/6/7  
 Bottom: \_\_\_\_\_

BROGDEN/ KILN CHART SAMPLE

You must be present when firing the electric kilns to make sure they shut off ... Sometimes they do not!

DAY	TIME		TEMP	Comments
DAY #1	3:00 PM		LOW LOW LOW	Small Cone 7 in sitter Cone Pack: 5/6/7  Top spie out Lower spies all in Timer to 20 hrs
	5:00 PM		LOW LOW MED	ALL SPIES IN
	8:00 PM		LOW MED MED	Over Night to Build Even Heat
DAY #2	8:00 AM		MED MED HIGH	TIMER TO 12 HOURS
	10:00 AM		MED HIGH HIGH	
	11:00 AM		HIGH HIGH HIGH	Start checking kiln every 30 minutes  When sitter or cones fall, turn all switches to OFF